

BLOWER MOTOR INSTALLATION NOTICE

WARNING

- SPARK PLUG WIRES MUST BE RETURNED TO THEIR ORIGINAL POSITION, A MINIMUM OF 1 INCH FROM THE HV A/C MOTOR EXTERIOR SURFACE FOLLOWING SERVICE.
- FAILURE TO DO SO MAY RESULT IN PREMATURE HVAC MOTOR FAILURE.