BLOWER MOTOR WHEEL REPLACEMENT NOTICE

The outside diameter and hub height may appear slightly different from the wheel being replaced. Increased blade pitch slightly enhances air movement without increasing noise.

UPDATED 08/2022 BOM# 85013553