

COMPRESSOR CLUTCH REPLACEMENT NOTICE

FORD CLUTCH INFORMATION SHEET

This clutch is interchangeable as a unit and may not look like the one being removed from the vehicle.

Since 1980, Ford has used three (3) different clutch suppliers for their 6 cylinder A/C compressors. (See drawing below). These clutches fully interchange, but individual components cannot be mixed from one type to the other. Doing so will cause clutch failure.

