## **RELAY INSTALLATION NOTICE**

This relay will replace the OE relay that has either 4 or 5 terminals. Modifications of the wiring harness connector will not be necessary.

UPDATED 08/2022 BOM# 85015988