SWITCH INSTALLATION NOTICE

Both large diameter (.565") and small diameter (.295") sensing bulbs have been used by the O.E. on this switch. G.M. currently supplies the large diameter only.

If the vehicle's original switch was the small diameter, any accumulated corrosion must be cleaned from the switch port in the water jacket to provide clearance for the larger diameter sensing bulb.

UPDATED 08/2022 BOM# 85015930